



EPA Refrigerant Conservation Services Report



Customer: DuPont Experimental Station

Date: 05/01/2019

Location: E315 Powerhouse

Equipment Type:	
Industrial Process / Com. Refrigeration	
Commercial - Over 50 lbs Refrigerant	<input checked="" type="checkbox"/>
Commercial-Under 50 lbs Refrigerant	

Equipment ID: CHILLER #8 (GACM117864)

Refrigerant Leak Verification Test

Source of Leak: _____

Corrective Action: _____

Source of Leak: _____

Corrective Action: _____

Source of Leak: _____

Corrective Action: _____

Source of Leak: _____

Corrective Action: _____

Initial Leak Verification Test : Pass Failed

Was Leak Repaired? Yes No Owner Declined Repair

Verification Test Method: _____

Refrigerant Usage

Refrigerant Type: (Circle One) R-11 R-12 R-22 R-123 R-134a R-407c R-410a Other:

Refrigerant Lbs. Used: 480 lbs Factory Charge or Approximate Charge: 3,250 lbs

Refrigerant Supplied By: Customer JCI Other, Explain _____

Refrigerant Recovery

(Technician Certification Cards on File at JCI Local Office)

Recovery Unit Model# YORK RTU-10 / 8416 Serial # 61795205-91012424 Mfg. Date Before 11/15/93 Yes / No

Refrigerant Type: (Circle One) R-11 R-12 R-22 R-123 R-134a R-407c R-410a Other:

Refrigerant Re-Charged to Sys.? Yes No Refrigerant Lbs. Recovered: _____

Refrigerant Not Re-Charged, Explanation: _____

Refrigerant Leak Rate Formula for Units Greater Than 50 Lbs

(480 lbs. Refrig. Added / 3,250 lbs. in Full Charge) x (365 / 298 # of Days Since Refrig. Added) x 100

Refrigerant Leak Rate Percent: 15.1% Minimal refrigerant leaks were found.

Leak Rate found in excess of 15% 35% annual charge which exceeds legal EPA leak rates.

30-Day Refrigerant Follow-up Verification Test

Date Test Performed: 02/25/2019 Pass Failed

Comments: Verified w/ Electronic Detector & Soap Bubbles (Chiller Pressure @ 70psig). After charge installed.

Additional Comments: _____

Technician Signature: [Signature]

Customer Signature: _____