

Title: 32MP I-O BOARD MOV COLOR

Number: C8910
Date: 6/29/89
Supersedes: NEW
Date:

Models Affected: 32MP

Purpose:

This bulletin provides information on the 32MP I-O board MOV's (metal oxide varistors) shipped after 4/89.

Background:

Bulletin C8904, dated 4/7/89 advised that green MOV's on 32MP I-O boards were misrated and had to be removed and replaced. The manufacturer of the board was able to get properly rated MOV's immediately but they were also green. Rather than confuse field personnel with "good" and "bad" green MOV's it was decided to dip "good" green MOV's in orange paint. The dipping process left small areas of green near the leads on some devices which has concerned a few observant people. Please be assured that only "good" green MOV's were painted and that the board supplier is inspecting all MOV's electronically to prevent a repeat of the problem.

AMJ/sm

FILE INSTRUCTIONS: CONTROLS-WIRING

MAIL KEYS: 2.33B, 2.33D, 2.40B, 2.45, 2.53, 5.14A, AND 5.14B

Prepared By: _____


Alan M. Johnson

Approved By: _____


James N. Cuny