



# SERVICE BULLETIN

SERVICE BULLETIN

Supersedes: Nothing

Form 160.49-M2 (SB12) (997)

File with form: 160.49-M2 (SJ4B Manual)

Subject: YK Centrifugal Chiller - Microcomputer Control Center  
Chinese Language Display

Beginning on/about April 1997, Chinese language displays will be supplied with either: two Simplified translation eproms or two Traditional translation eproms. If Simplified translation is desired, both of the Simplified eproms below are required. If Traditional translation is desired, both of the Traditional eproms below are required. The eprom part numbers and on-board socket locations are as follows:

<u>EPROM</u>	<u>TRANSLATION</u>	<u>SOCKET LOCATION</u>
031-01700-001	Simplified	U13
031-01700-002	Simplified	U14
031-01700-003	Traditional	U13
031-01700-004	Traditional	U14

Previously, Chinese Language displays contained one eprom (031-01640-001) (socket location U13) that translated to Simplified Chinese and one eprom (031-01640-002) (socket location U14) that translated to Traditional Chinese. The desired translation was then selected by program jumper PT0, located on the Chinese language display board. Due to the addition of messages, two eproms are now required for each translation as described above. When equipped with these new eproms, Program Jumper PT0 can no longer be used to select between Simplified or Traditional translation. If one of the earlier version eproms fail, refer to renewal parts list 160.49-RP3 for replacement.

S.L. Baer  
York Factory Service