JOHNSON CONTROLS

Service Agent ID: Frazek

Page 1 of 1

Customer Name: DuPont E315 Powerhouse

Service Order Number: 260-1006812

Bill To ☐ Same as above

Equipment ID (Tag ID): ABS #3

Work Site: Experimental Station

Problem: Alarm Shutdown

Work Site Address:

Contact Name/Phone: Tom Sliwinski

Additional Billing Information

TROUBLESHOOT #4 YORK ABS Chiller AT E315/Powerhouse

Quoted Price/Flat Rate $ _____ Resolved? ☑ Yes Date 6/18/07 ☐ No

Type of Service:
☑ T&M ☐ No Charge ☐ RAC ☐ PSA# _____ ☐ Warranty to Installation # _____ ☐ Warranty to S.O. # _____

PAYMENT AUTHORIZATIONS

Purchase Order Number	Printed Name	Signature
LGGC 115TS	X THOMAS SLIWINSKI	X

Credit Card Type	Card Holder Name	Card Number	Expiration Date
☐ MC ☐ VISA ☐ AMEX			/

ACTIVITIES

Service Agent ID	Activity Type	Reg. Hours	1.5 OT Hrs.	2.0 OT Hrs.
Frazek	MC	3		

Date	Miles/Km	Expenses	Explanation
6/18	30	$	

Service Agent ID	Activity Type	Reg. Hours	1.5 OT Hrs.	2.0 OT Hrs.

Date	Miles/Km	Expenses	Explanation
		$	

Service Agent ID	Activity Type	Reg. Hours	1.5 OT Hrs.	2.0 OT Hrs.

Date	Miles/Km	Expenses	Explanation
		$	

Service Agent ID	Activity Type	Reg. Hours	1.5 OT Hrs.	2.0 OT Hrs.

Date	Miles/Km	Expenses	Explanation
		$	

Service Agent ID	Activity Type	Reg. Hours	1.5 OT Hrs.	2.0 OT Hrs.

Date	Miles/Km	Expenses	Explanation
		$	

COMMENTS

Chiller could not be restarted due to FLS alarm. During the last shutdown Chilled water flow was lost before dilution was complete. Reset alarm, started and monitored performance. Chiller ok at this time.

MATERIALS

PO #: Truck #: F/O #	Vendor	Qty.	Description	Part #
		1	Consumable Materials	CSM-1

PUBL-3444 (01/04)

White copy - ORIGINAL Pink copy - FLSP Yellow copy - CUSTOMER