UNITED TECHNOLOGIES CARRIER	Commercial Division Carrier Corporation	BULLETIN: CA-SB-19-D-90-119 DATE: 2/2/90 PAGE: 1 OF: 1
SERVICE BULLETIN		SUPERSEDE BULLETIN: DATE: PAGE: OF:
SUBJECT: 32MP660-010 EPROM KIT		

Installation, repair and service and equipment referenced in this Service Bulletin should be undertaken only by qualified persons. Carrier Corporation (1) makes no representations or warranties, expressed or implied, concerning the accuracy, completeness or right to use the information contained herein, and (2) disclaims all liability for injuries, damages, infringements and other losses which may arise on account of, or which may result from, the use or application of any information, method or apparatus disclosed herein.

PURPOSE

This bulletin provides information on 32MP EPROMs from the Replacement Components Division that have not been marked with the correct Carrier part numbers.

MACHINES AFFECTED

All 17/19 series machines with 3200MP Controls

BACKGROUND

It has been brought to our attention that the EPROMs in kit number 32MP660-010 may not be marked with the Carrier part number but rather with our vendor's part number. The kits affected are marked with date code K/9. The date code is in the lower left-hand corner of the RCD label.

Below is a cross-reference from our vendor part numbers to Carrier's part numbers in order to identify the EPROMs.

Vendor Part Number	Carrier Part Number
HT204911-1-12	HK98EZ006
HT204779-1-14	HK98EZ015
HT205935-1-13	HK98EZ023

RECOMMENDATION

Please re-label the EPROMs before they are installed for easier identification.

Copyright ©Carrier Corporation 1983