



**UNITED
TECHNOLOGIES
CARRIER**

Commercial Division
Carrier Corporation

BULLETIN: CA-SB-19-C-78-90
DATE: 3/1/78
PAGE: 1 OF 1

SERVICE BULLETIN

SUBJECT: 7LI COMPRESSION-TYPE PURGE PUMP
MOTOR LUBRICATION

SUPERSEDE
BULLETIN:
DATE:
PAGE: OF:

Installation, repair and service and equipment referenced in this Service Bulletin should be undertaken only by qualified persons. Carrier Corporation (1) makes no representations or warranties, expressed or implied, concerning the accuracy, completeness or right to use the information contained herein, and (2) disclaims all liability for injuries, damages, infringements and other losses which may arise on account of, or which may result from, the use or application of any information, method or apparatus disclosed herein.

PURPOSE

To emphasize that the 7LI compression-type purge pump motor must be lubricated at regular intervals.

MACHINES AFFECTED

19C machines with the 7L1 compression-type purge.

INFORMATION

Lubrication of the 7L1 compression-type purge pump motor is provided by an oil cup at each bearing.

The machine operator should be reminded to lubricate these bearings every six months during the cooling season to insure trouble-free operation. He should also be cautioned that, to allow time for complete absorption of the oil by the wool yarn packing in each oil cup, *the oil must be added slowly to avoid over-lubrication.*