

Title: 32MP660010 EPROM KIT

Number: C9002

Date: 02/02/90

Supersedes:

Date:

Models Affected:

32MP

Purpose:

This bulletin provides information on 32MP EPROMs from RCD that have not been marked with the correct Carrier part numbers.

Background:

It has been brought to our attention that the EPROMs in kit 32MP660010 are not marked with the Carrier part number. However, they are marked with our vendor's part number. The kits affected are marked with date code K/9. The date code is in the lower left hand corner of the RCD label.

Below is a cross reference from our vendor part numbers to Carrier's part numbers in order to identify the EPROMs.

<u>VENDOR PART NUMBER</u>	<u>CARRIER PART NUMBER</u>
HT204911-1-12	HK98EZ006
HT204779-1-14	HK98EZ015
HT205935-1-13	HK98EZ023


Recommendations:

Please re-label the EPROMs before these go out into the field for easier identification.

FILE INSTRUCTIONS: CONTROLS/WIRING

MAIL KEYS: 2.33B, 2.33D, 2.40B, 2.45, 2.53, 5.14A

Prepared By:



Donald W. Berdan

Approved By:



Alan M. Johnson