



SERVICE BULLETIN

Title: VaporSaver Flange Gaskets

Number: C9510

Models Affected: New Installations And Service Work

Date: 7/7/95

Supersedes: New

Date:

Purpose:

To advise of a new material for the flange gaskets used on VaporSaver.

File: Cooler-Condenser-Economizer

Prepared By: Richard Martin

Approved By: Alan Johnson

This document and the material contained herein are the property of Carrier Corporation and may not be copied, reproduced, or released without written permission of Carrier Corporation.

Background:

There have been occasional reports of the neoprene impregnated cork gaskets having occasional leaks.

Procedure:

Use the 4" flange gasket part number CT99QX601 for replacement and new installations of Vapor-Saver. This gasket is made of Garlock 3300. The bolt torque will remain the same at 52 ft.-lbs.

It is not necessary to replace all cork gaskets. If leaks or degradation of the cork gaskets are experienced, then use the CT99QX601 as a replacement. This gasket is thinner, 1/16".