



SERVICE BULLETIN

SERVICE BULLETIN

Supersedes:Nothing

Form 160.49-M2 (SB20)(698)

File With 160.49-M2

SUBJ.: PRINTER READINGS ARE ALL ZERO (0)

PROBLEM: WHEN USING ANY OF THE APPROVED YORK PRINTERS ON ANY OF THE ABOVE CHILLERS, YOU EXPERIENCE THAT THE PRINT OUT SHOWS ALL ZERO'S AFTER THE DEVICE / COMPONENT DESCRIBED.

SOLUTION: 1. THE CHILLER HAS NOT RUN, THEREFORE THERE IS NOTHING STORED IN THE BUFFER ON THE MICRO BOARD, THUS ALL READINGS WILL BE ZERO ON THE PRINTOUT.

2. ALSO CHECK:

- A. DIP SWITCH SETTINGS ON THE PRINTER**
- B. CHECK THE JUMPER ON THE MICRO BOARD TO ASSURE IT IS IN THE PROPER POSITION.**
- C. RE-CHECK THE WIRING OF THE PRINTER TO THE PANEL.**