



**District Cost:**

Cost to the district may be found in **Table 100**. Total cost of VentGuard II in the table (not including VentAlarm) is a summary of items 1 through 3 as indicated above.

**Field Purchased Items:**

Based on field trial installations, the purchase of some field items may be necessary. Review each job with these items in mind:

- Ceiling Hangers for VentGuard II or Piping
- Other types of piping supports such as floor mounts
- Various types of pipe fittings including unions, flanges, elbows, etc.
- Wiring and alarm devices for connecting to and receiving from  
VentAlarm

**Service Replacement Parts:**

Service replacement parts may be obtained from the PDC at standard replacement parts pricing. Those parts available are:

- |                              |               |
|------------------------------|---------------|
| - Relief Valve HLCB 4"       | 026-32825-008 |
| - Excess Flow Valve          | 026-32825-027 |
| - Bursting Disk              | 026-32825-025 |
| - Gasket Replacement Set (4) | 026-32825-010 |
| - O-Ring HLCB Valve          | 026-32825-011 |

