



ES Service Information

File In/With: N/A

SI0086

New 4-04

Equipment Affected: ECO2 (YPAL) Rooftop Units

Availability of Repair Parts Manuals



Replacement parts manuals are now available for the YPAL 50-95 rooftop product.

Form 100.50-RP1 (404)

This contains replacement parts information for the YPAL control panels. The manual is broken down into three major sections.

- Section 1 contains information on the Fan Sub Panels;
- Section 2 covers information for the Power Panels,
- Section 3 contains information on Unique Panel Kits.

Form 100.50-RP2 (304)

This contains information on all unit parts that are not part of the main control panel.

Parts information for the new modulating heat and return air fan options also are contained in the manuals.

These manuals are available (5/3/04) through the Publications Distribution Center, or both manuals can now be accessed via the YORK intranet under YorkWorks Library/Commercial Systems Products/Eco² Rooftop Unit.