



SERVICE BULLETIN

SERVICE BULLETIN

Supersedes: Nothing

Form 155.17-M2 (SB10)(798)

File With 155.17-M2

SERVICE BULLETIN

SUBJ.: PRINTER READINGS ARE ALL ZERO (0)

**FILE IN: YT,YK,YS,YG,YB.PARAFLOW, ISO FLOW
SERVICE MANUALS**

PROBLEM: WHEN USING ANY OF THE APPROVED YORK PRINTERS ON ANY OF THE ABOVE CHILLERS, YOU EXPERIENCE THAT THE PRINT OUT SHOWS ALL ZERO'S AFTER THE DEVICE / COMPONENT DESCRIBED.

SOLUTION: 1. THE CHILLER HAS NOT RUN, THEREFORE THERE IS NOTHING STORED IN THE BUFFER ON THE MICRO BOARD, THUS ALL READINGS WILL BE ZERO ON THE PRINTOUT.

2. ALSO CHECK:

- A. DIP SWITCH SETTINGS ON THE PRINTER
- B. CHECK THE JUMPER ON THE MICRO BOARD TO ASSURE IT IS IN THE PROPER POSITION.
- C. RE-CHECK THE WIRING OF THE PRINTER TO THE PANEL.