

Carrier Controls

32Mp

PIC Controls

Carrier Microprocessor

32 MP Controls

32MP	Familiarization Operation Sequence	021-022
32MP	Start-Up Troubleshooting	021-024
32MP	ESP I Operation and Maintenance	533-210
32MP	ESP II Operation and Maintenance	021-013
32MP	ESPII	533-211
32MP	Display Codes and Test Points	
32MP	Hand Out	
	Microprocessor Hand Out	
32MP	Thermistor Charts	
32MP	Simulator Hand Out	
32MP	v.s. P.I.C Hand Out	

32MP Service Bulletins

SB-19-D-87-106	3200MP Software Changes
SB-19-D-87-107	ESP Configuration and Operating Parameters
SB-19-D-88-109	ESP Replacement Panels
SB-19-D-88-113	3200MP Troubleshooting
SB-19-D-89-116	32MP I/O Board Failure
SB-19-D-89-117	32MP Control Panel Grounding
SB-19-D-90-118	3200MP Molex Trifurcon Terminals
SB-19-D-90-119	32MP 660-010 Eprom Kit
SB-19-D-90-121	32MP Retrofit with Honeywell Guide Vane Actuator
SB-19-D-90-122	32MP Control Improvements
SB-19-D-90-126	32MP/ESP Start-Up and Operation Revisions
SB-19-D-90-127	Aux. Relays for 32MP Controllers
C9310	3200MP Chiller Gateway
C9311	3200MP Complete Parts Listing
C9316	3200MP Code 97

Carrier Microprocessor

P.I.C Controls

19XL	Start-Up, Operation and Maintenance	531-971
19XL	With P.I.C. Familiarization User Operations Start-Up Shutdown Troubleshooting	021-900
19XR	Hermetic Centrifugal Liquid Chiller	531-955
P.I.C.	Retrofit Kits for Centrifugal Chillers	531-724
19XR,XRV	Hermetic Centrifugal Chiller R-123a with P.I.C. II	531-982

P.I.C. Service Bulletins

C9318	LID Service Password
C9406	Starter Optional KW Meter Calibration
C9409	19XL PSIO Software Version 9
C9502	SMM and 8-Pin Module Lockup
C9603	17/19/23 PSIO II Hardware and Software
C9604	23XL Version 14 Software
C9605	23XL PSIO Installation Instructions
C9610	19XL Version 10 Software
C9612	19EF/EX/FA Version 3 Software
C9614	Temperature Sensors
C9617	17EX/FA Version 1 Software
C9620	Control Transformer Backfeed
C9623	Battery Replacement for PSIO/LID -1B
C9624	LID -2B Display for PIC Controls
C9628	Corroding Sensors
C9632	IQ 1000II Default Settings and Calibration
C9721	23XL Version 15 Software
C9725	19XL Version 11 Software
C9728	Solid State Starter Electrical Isolation Requirements
C9734	Year 2000 Date Change
C9736	Compressor PIC Discharge Sensor Replacement
C9810	PIC R-134a Retrofit Kit
C9813	Benshaw, SMM-less Starter Shunt Trip Reset
C9814	PSIO to CCM Wiring
C9831	PIC II Controls Familiarization
C9905	PIC Communications Interruption
C9906	PSIO II Hardware and Software Part Numbers
C9911	Starter Manufacturer Assistance

C9917 Centrifugal Chiller PIC Y2K Remediation
C9918 19XR PIC II CVC Software Version 03
C9920 ISM Changes, Version 4
C0005 Version 12 Software for PIC II Benshaw Starters
C0007 DC Volt Analog Inputs, PIC II Controls
C0008 19XR PIC II software, Version 04
C0013 Compressor PIC Discharge Sensor Replacement
C0103 ISM Transition with Wye-Delta Starter
C0109 Brass water Side Pressure Transducers for PIC II
C0111 PIC Thermistor Thermowells
C0113 Head Pressure Reference from PIC II Benshaw Starters