

Title: 17/19/23 PSIO II HARDWARE AND SOFTWARE P/N

Number: C9603
Date: 1/26/96
Supersedes:
Date:

Models Affected: 17EX, 17FA, 19EF, 19EX, 19FA, 19XL, 19XT AND 23XL

PURPOSE:

To provide information to the field about the latest changes to the PSIO p/n HK50AA020. The new PSIO II p/n HK50AA023 has superior, more robust electrical hardware.

The following are p/n of the PSIO I and PSIO II downloaded with latest software.

| Chiller Model | Software Version & Date | PSIO I P/N | PSIO II P/N |
|---------------|-------------------------|--------------|--------------|
| 17EX/FA | 01 01/08/96 | N/A | 17EX54001801 |
| 19EX/EF/FA | 03 01/08/96 | N/A | 19EX54001901 |
| 19XL,XT | 10 01/08/96 | 19XB04002601 | 19XB04008501 |
| 23XL | 14 * 11/28/95 | 23XL04000101 | 23XL04007001 |

* Note: When using 23XL PSIO module with software Version 14 or higher to replace an earlier version of software, wiring modifications must be performed. Instructions are include with replacement modules.

The PSIO II hardware will be available to the field from RCD in February 1996 after the PSIO I stock is depleted. During the transition period some of the chillers were shipped from factory with PSIO I hardware with PSIO II p/n. These do not need to be changed.

Field Action:

Replace the PSIO on all 17EX and 17FA chillers with PIC controls shipped from factory prior to 01/01/96 with the latest software.

Other individual product bulletins will address specific software changes.

FILE: Controls

Prepared By: 

NICK CHASHIN

Approved By: 

ALAN M. JOHNSON

MAIL KEYS: 2.40A, 2.40M, 2.40I, 2.40J, 2.40G, 2.40, 5.25G, 2.33A, 2.33B, 2.33C