



ParaFlow Service Bulletin

SERVICE

Supersedes:155.17-RP1(SB1)(1294)

595

Form:155.17-RP1 (SB1)

Date : May 4, 1995
To : District Offices
Subject : Renewal Parts (REVISED)
Units Affected : ParaFlow™ Absorption Units

New Spare Parts Available

There are several new items available for ParaFlow units and rather than wait until the RP manual is revised, we are listing them in this Service Bulletin.

Replacement Rupture Disk Gaskets

4 inch disk gaskets: (2 gaskets required) 026-33818-000

6 inch disk gaskets: (2 gaskets required) 026-33819-000

Nikkiso Pump Gaskets (U.S. Made gaskets without purchasing the overhaul kits.)

Nikkiso Model Number	Volute Hsg. Gasket	Motor Hsg. Gasket
S291-.8/1.5	028-12589-000	028-12586-000
SS291-2.2	028-12590-000	028-12586-000
SS230-3.7	028-12590-000	028-12587-000
SS231-3.7	028-12590-000	028-12587-000
SS231-4.5	028-12590-000	028-12587-000
SS221-5.5	028-12591-000	028-12587-000
SS491-3.7	028-12593-000	028-12588-000
SS491-5.5	028-12593-000	028-12588-000
SS491-7.5	028-12593-000	028-12588-000
SS491-1.5	028-12592-000	028-12587-000
S491-1.5	028-12591-000	028-12587-000

Kits for Double Ended NIKKISO Solution Pump used on 13S and 14S Units

Overhaul Kit: (Hitachi p/n PP8000) 026-33816-000

Insulation Kit (Hitachi p/n PP8001) 026-33817-000

Buffalo Pump

Casing Gasket (215R,215Z,66V 8011 type): 028-12599-000

Casing Gasket (66M 709): 028-12700-000

Note: Recent design pumps use an O-Ring instead of a flat gasket. Both the O-Ring and a gasket will be supplied when ordering either of the above casing gaskets. Use only the one that matches what was in the pump.

Pump Kit (includes impeller wear rings, impeller fastening hardware and gasket for 66V-8011 pump): 026-32832-000

Note: that other pump kits and bearing kits are listed in 155.17-RP1

Diaphragm Valve (1/2 inch SS socket weld type)

Replacement Neoprene Diaphragm: 022-09125-000

Replacement Bonnet Assbly: 022-09126-000

Spindle Valves

Sample Valve O-Ring Repair Kit (caps and spindle): 028-12271-001

1/2 inch Flow Setting Valve O-Ring Repair Kit: 028-12271-002

1 1/2 inch Flow Setting Valve O-Ring Repair Kit: 028-12271-004

Globe Valves (Seal Cap Type)

Repair Kits (includes cap gasket and stem packing)

1.5 inch — 022-08869-029

2 inch — 028-12271-025

2.5 inch — 028-12271-026

3 inch — 028-12271-027

4 inch — 028-12271-028

Honeywell Steam Valve Actuator Motor:

Motor for (2.5, 3 and 4 inch Steam Valves): 024-26512-000