

	File in 2SAM, RJM Manual(s)	
SERVICE BULLETIN	Supersedes: Nothing	Form 155.17-RP1 (SB5)
File with Form: 155.17-RP1		

**SUBJECT: YPC PARAFLOW ABSORPTION CHILLER –
MICROCOMPUTER CONTROL CENTER PARTS LIST REVISION**

Micro Board part number 031-01065-001 will no longer be produced for new production and no longer provided for service replacement when present stock is extinguished. Part number 031-01065-002 will be provided in its place.

Micro Board part number 031-01065-002 is identical to -001 except that a circuit was added to output an oil pump Pulse Width Modulation (PWM) speed command from J10-2 for YK centrifugal chiller applications with variable speed oil pump.



S. L. Baer
YORK Factory Service