

Frazek

Customer Name *DuPont Experimental Station*

Service Order Number **260-1006179**

Bill To  Same as above

Equipment ID (Tag ID) *Chiller #8*

Work Site *E315 Powerhouse*

Problem *Refrigerant Leaks*

Work Site Address *Wilmington, DE*

Contact Name/Phone *Tom Slivinski*

Additional Billing Information

Quoted Price/Flat Rate \$ \_\_\_\_\_ Resolved?  Yes Date 3/30/07  No

Type of Service:

T&M  No Charge  RAC  PSA# \_\_\_\_\_  Warranty to Installation # \_\_\_\_\_  Warranty to S.O. # \_\_\_\_\_

**PAYMENT AUTHORIZATIONS**

Purchase Order Number \_\_\_\_\_ Printed Name *Tom Slivinski* Signature \_\_\_\_\_

Credit Card Type  MC  VISA  AMEX Card Holder Name \_\_\_\_\_ Card Number \_\_\_\_\_ Expiration Date 1

**ACTIVITIES**

**COMMENTS**

Service Agent ID Activity Type Reg. Hours 1.5 OT Hrs. 2.0 OT Hrs.

*Frazek* *ML* \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_

Date Miles/Km Expenses Explanation

*3/28-30* \_\_\_\_\_ \$ \_\_\_\_\_

*Repaired extra refrigerant leaks found on the chiller after oil line work was finished.*

Service Agent ID Activity Type Reg. Hours 1.5 OT Hrs. 2.0 OT Hrs.

\_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_

Date Miles/Km Expenses Explanation

\_\_\_\_\_ \$ \_\_\_\_\_

*Leaks!  
High Speed Thrust Cover O-Ring  
Oil Cooler Liquid Feed Threaded T  
Suction Free-Cooling Butterfly Gasket*

Service Agent ID Activity Type Reg. Hours 1.5 OT Hrs. 2.0 OT Hrs.

\_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_

Date Miles/Km Expenses Explanation

\_\_\_\_\_ \$ \_\_\_\_\_

Service Agent ID Activity Type Reg. Hours 1.5 OT Hrs. 2.0 OT Hrs.

\_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_

Date Miles/Km Expenses Explanation

\_\_\_\_\_ \$ \_\_\_\_\_

Service Agent ID Activity Type Reg. Hours 1.5 OT Hrs. 2.0 OT Hrs.

\_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_ \_\_\_\_\_

Date Miles/Km Expenses Explanation

\_\_\_\_\_ \$ \_\_\_\_\_

**MATERIALS**

PO #: Truck #: F/O #	Vendor	Qty.	Description	Part #
		1	Consumable Materials	CSM-1