

Frazek

Customer Name Dubout E315

Service Order Number 260-1006548

Call To Same as above

Equipment ID (Tag ID) Chiller #7

Work Site Experimental Station

Problem Motor Oil Pressure Too High

Work Site Address Wilmington, DE

Contact Name/Phone Tom Slawinski

Additional Billing Information

Quoted Price/Flat Rate \$ _____ Resolved? Yes Date 5/21/07 No

Type of Service:
 T&M No Charge RAC PSA# _____ Warranty to Installation # _____ Warranty to S.O. # _____

PAYMENT AUTHORIZATIONS

Purchase Order Number LG6C099TS Printed Name X Signature X

Credit Card Type MC VISA AMEX Card Holder Name _____ Card Number _____ Expiration Date 1

ACTIVITIES

Service Agent ID	Activity Type	Reg. Hours	1.5 OT Hrs.	2.0 OT Hrs.
<u>Frazek</u>	<u>MC</u>	<u>2</u>	<u>2</u>	

COMMENTS
Started chiller. Monitored and adjusted pressure to motor bearings. Fixed leak on compression fitting.

Date	Miles/Km	Expenses	Explanation
<u>5/21</u>	<u>40</u>	<u>\$</u>	

Service Agent ID	Activity Type	Reg. Hours	1.5 OT Hrs.	2.0 OT Hrs.

Date	Miles/Km	Expenses	Explanation
		<u>\$</u>	

Service Agent ID	Activity Type	Reg. Hours	1.5 OT Hrs.	2.0 OT Hrs.

Date	Miles/Km	Expenses	Explanation
		<u>\$</u>	

Service Agent ID	Activity Type	Reg. Hours	1.5 OT Hrs.	2.0 OT Hrs.

Date	Miles/Km	Expenses	Explanation
		<u>\$</u>	

Service Agent ID	Activity Type	Reg. Hours	1.5 OT Hrs.	2.0 OT Hrs.

Date	Miles/Km	Expenses	Explanation
		<u>\$</u>	

MATERIALS

PO #: Truck #: F/O #	Vendor	Qty.	Description	Part #
		<u>1</u>	<u>Consumable Materials</u>	<u>CSM-1</u>